

615

No. _____ Survey held at London Date Oct 75 184 / 9670

on the Ship mounted East of the Master _____

Tonnage 600 Built at _____ When built _____

By whom built _____ Owners _____

Port belonging to London Destined Voyage _____

If Surveyed Afloat or in Dry Dock Fletcher Dry Dock

Original Survey, No. _____ Port of _____ Classed _____

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirkettling _____	Topsides _____	Sails _____
Plank Shears _____	Wales _____	Cables _____
Waterways _____	Plank and Treenails _____ (Outside to the Water's Edge)	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass &c. _____	Copper _____

General Observations and Opinion,
as required by the Instructions,

Examined and overhauled
Rigging - Good sufficient

Committee Minute _____ 184

Character assigned _____

George Beagley



© 2019

Lloyd's Register
Foundation