

615

947

REPORT of SURVEY for REPAIRS.

No. _____ Survey held at London Date June 2 1837
 on the Ship Charlotte Master W. H. Smith
 Tonnage 611 Built at Bombay When built 1821
 By whom built _____ Owners Heathcote
 Port belonging to London Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Mr. Fletcher Dry Dock

Original Survey, No. _____ Dated _____
 Port _____

Repairs. *at the present time caulked from the keel up and
 sheathed with Yellow Metal -
 The Topsides scraped bright all in good order*

The Surveyor to state the present Condition of

Upper Deck Fastenings	_____	Wales	_____
Spirkettling	_____	Counter	_____
Plank Shears	_____	Plank and Treenails (Outside to the Water's Edge.)	_____
Topsides	<i>Good</i>	Rudder	<i>Good</i>
Upper Deck with its Appendages	_____	Winlass	_____
Lower Deck Fastenings	_____	Capstan	_____

Masts, Sails & Rigging overhauling.

General Observations and Opinion, *This ship is in a good and efficient*
 as required by the Instructions, *State of repair throughout*
George Bayley

The Amount of Fee.....£ : : is received by me.

Committee Minute _____ 183 _____

Character assigned _____