

# ANNUAL SURVEYS.

9697  
11

No. 747 Survey held at London Date April 24<sup>th</sup> 1843  
 on the Schooner Sultan Master Barrow  
 Tonnage 91 Built at Plymouth When built 1835  
 By whom built Plymouth Owners Gent  
 Port belonging to Plymouth Destined Voyage  
 If Surveyed Afloat or in Dry Dock For and aft ways

Original Survey, No. 57, 116, 435, 753 Port of Plymouth 1839 Classed 11A1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, This vessel having wrinkled and strained her keel abaft as  
 as required by the Instructions, if she had been ashore left on the 24<sup>th</sup> and recommending  
that the three or four seams above the keel abaft should  
be shipped and caulked - the recommendation has not been  
attended to - The yellow metal is largely  
repaired to the vessel is proceeding to sea -  
 Committee Minute 2nd May 1843  
 Character assigned Exempt In my opinion she is very likely to become  
leaky if she meets with heavy weather brought  
down by a gale - she has been shipped and caulked to repair  
the damage evidently sustained George Bayley  
2nd May 1843

No. 72 Survey held at London Date March April 24<sup>th</sup> 1843  
 on the Steam Vessel Waterwitch Master at Gibson  
 Tonnage 276 Built at London When built 1835  
 By whom built Curling & Co Owners General Steam Co  
 Port belonging to London Destined Voyage Stull  
 If Surveyed Afloat or in Dry Dock Blackwall & London Bridge

Original Survey, No. 570, 810, 869, 815, 8270, 9141 Port of London October 1841 Classed 12A1

The Surveyor is required to state the present Condition of the

Decks <u>Shipped after gangway</u>	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, Shipped. Caulked keel - bricoppered to 9.9 - The  
 as required by the Instructions, Deck shipped on each side over after spencings - and generally  
overhauled - In my opinion she is eligible to  
remain as classed 12A1  
 Committee Minute 2nd May 1843  
 Character assigned 10A1 George Bayley  
10A1