

ANNUAL SURVEYS.

9796

No. 5 Survey held at London Date May 4th 16 1843
 on the St. Andrew Master Haddock & Hallen
 Tonnage 132 Built at Leppham When built 1832
 By whom built _____ Owners Rogers
 Port belonging to London Destined Voyage Halifax
 If Surveyed Afloat or in Dry Dock Mountain Slip

Original Survey, No. 991 Port of London April 1842 Classed 12A1

The Surveyor is required to state the present Condition of the

Liv. 3575, Lin 7490, 7610, 8623.

Decks	<u>Good</u>	Transoms	<u>Good</u>	Capstan	
Upper Deck Beams & Fastenings	<u>4</u>	Timbers of the Frame	<u>4</u>	Pumps	<u>Good</u>
Lower Deck Beams & Fastenings	<u>4</u>	Topsides	<u>4</u>	Masts, Yards, &c.	<u>Good & Efficient</u>
Spirkettling	<u>4</u>	Wales	<u>4</u>	Sails	<u>See see</u>
Plank Shears	<u>4</u>	Counter	<u>4</u>	Cables	<u>See see</u>
Waterways	<u>4</u>	Plank and Treenails (Outside to the Water's Edge.)	<u>4</u>	Anchors No. of	<u>2 1 1</u>
Hatchway Comings	<u>4</u>	Rudder	<u>See Rudder fitted</u>	Standing & Running Rigging	<u>Good</u>
Breasthooks	<u>4</u>	Windlass	<u>4</u>	Copper	<u>Smooth</u>

General Observations and Opinion, The vessel appears to be in good condition and
 as required by the Instructions, eligible to remain as classed 12A1

Committee Minute 13th June 1843

Character assigned 12A1

George Bayley

[Signature]

No. Duplicate Survey held at London Date May 6th 15 1843
 on the St. Prospero Master Blyth
 Tonnage 117 Built at Wiscushee When built 1841
 By whom built Harvey Owners Johnston
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Mountain Slip

Original Survey, No. _____ Port of London May 1842 Classed 12A1

The Surveyor is required to state the present Condition of the

Decks		Transoms		Capstan	
Upper Deck Beams & Fastenings		Timbers of the Frame		Pumps	
Lower Deck Beams & Fastenings		Topsides		Masts, Yards, &c.	
Spirkettling		Wales		Sails	<u>Good & Efficient</u>
Plank Shears	<u>Good</u>	Counter	<u>Good</u>	Cables	
Waterways		Plank and Treenails (Outside to the Water's Edge.)		Anchors No. of	
Hatchway Comings		Rudder		Standing & Running Rigging	
Breasthooks		Windlass		Copper	

General Observations and Opinion, Starboard & Fore Channel & Chum flutes refitted
 as required by the Instructions, Starboard Plank shee. Waterway Bulwark and
Hauteuts round Starboard Bow - all damages
efficiently repaired - In my opinion this eligible
to remain as classed 12A1

Committee Minute 184

Character assigned _____

George Bayley

© 2019

Lloyd's Register
Foundation