

9811
JL

REPORT of SURVEY for REPAIRS.

No. 297 Survey held at London Date May 4 8 13 14 24 1843
 on the William Fulcher Master Wm Stearns
 Tonnage 225 Built at Rochester When built 1839
 By whom built — Owners Rockley, Georgiana Terrace
 Port belonging to London Destined Voyage —
 If Surveyed Afloat or in Dry Dock In Dry Dock Old Kent Road

Original Survey, No. 5633, 5760 Dated 1656 Classed A1
 Port London

REPAIRS

At the present time from damage ^{after} two lengths of
 main keel new some beams shifted new false keel
 re-constructed the ceiling coarced from the keel up
 30 from hanging knees to upper deck beams and
 6 to hold beams. as opposed to the water,

Present Condition of the		
Decks <u>Good</u>	Transoms <u>Good</u>	Windlass <u>Good</u>
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>do</u>	Capstan <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>do</u>	Pumps <u>do</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Masts, Yards, &c. <u>Sufficient</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Sails <u>Good</u>
Waterways <u>do</u>	Plank and Treenails (Outside to the Water's Edge) <u>do</u>	Cables <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Anchors No. of <u>do</u>
Breasthooks <u>do</u>	Copper <u>May 1843</u>	Standing & Running Rigging <u>do</u>

General Observations and Opinion, She is now in an efficient condition
and may remain so closed

Howland
J. H. Ritchie

The Amount of Fee.....£ 1 : — : — is received by me, LL

Committee's Minute 16th June 1843

Character assigned 10 A 1 2000

