

# ANNUAL SURVEYS.

9853

No. 691 Survey held at London Date 20th June 1843  
 on the Mr. Commodore Master Hore  
 Tonnage 203 Built at Newport When built 1835  
 By whom built — Owners N. J. Smith & Co  
 Port belonging to London Destined Voyage Home  
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 1020 Port of Sunderland, Lon 4440, Classed 12A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>—</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>No</u>	Pumps <u>Sufficient &amp; Good</u>
Lower Deck Beams & Fastenings <u>No</u>	Topsides <u>No</u>	Masts, Yards, &c. <u>No</u>
Spirketting <u>Good</u>	Wales <u>No</u>	Sails <u>No</u>
Plank Shears <u>Good</u>	Counter <u>No</u>	Cables <u>No</u>
Waterways <u>No</u>	Plank and Treenails <u>No</u>	Anchors No. of <u>No</u>
Hatchway Comings <u>No</u>	(Outside to the Water's Edge.)	Standing & Running Rigging <u>No</u>
Breasthooks <u>No</u>	Rudder <u>No</u>	Copper <u>Good</u>
	Windlass <u>No</u>	

General Observations and Opinion,

as required by the Instructions, Fastenings are firm and the ship appears strong both in an efficient condition may remain as Classed

Committee Minute 30th June 1843

Character assigned 12A1

No. 140 Survey held at London Date 21 June 1843  
 on the Mr. Henry Werry Master Dave  
 Tonnage 199 Built at Bridport When built 1842  
 By whom built 2nd Mr. Cox Owners Sam  
 Port belonging to London Destined Voyage Lima  
 If Surveyed Afloat or in Dry Dock —

Original Survey, No. 79 Port of Bridport, Weymouth, Classed 9A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>—</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>No</u>	Pumps <u>Sufficient &amp; Good</u>
Lower Deck Beams & Fastenings <u>No</u>	Topsides <u>No</u>	Masts, Yards, &c. <u>No</u>
Spirketting <u>Good</u>	Wales <u>No</u>	Sails <u>No</u>
Plank Shears <u>No</u>	Counter <u>No</u>	Cables <u>No</u>
Waterways <u>No</u>	Plank and Treenails <u>No</u>	Anchors No. of <u>No</u>
Hatchway Comings <u>No</u>	(Outside to the Water's Edge.)	Standing & Running Rigging <u>No</u>
Breasthooks <u>No</u>	Rudder <u>No</u>	Copper <u>Yellow Metal 14 3/4 Lbs</u>
	Windlass <u>No</u>	

General Observations and Opinion,

as required by the Instructions, Now Caulked from the Keel up to the Gunwale and Sheathed with yellow metal to the Wale is in an efficient state and may remain as Classed

Committee Minute 30th June 1843

Character assigned 9A1



© 2019

Lloyd's Register Foundation