

ANNUAL SURVEYS.

9875

No. ¹⁹⁵ 195 Survey held at London Date 7th July 1843
 on the Agnes Master Cratchfield
 Tonnage 207 Built at Dumbarton When built 1825
 By whom built — Owners Buller
 Port belonging to London Destined Voyage Spain
 If Surveyed Afloat or in Dry Dock on the ways & afloat

Original Survey, No. 706 Port of Liverpool, Lon 3860, 5370, 6102, Classed F.1
6612, 7737, 9111.

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>good where seen</u>	Pumps <u>good</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>good</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>do</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>meddling</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>large bottom, &c.</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>main not good</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>good</u>	Windlass <u>do</u>	Copper <u>none for many years</u>

General Observations and Opinion,
 as required by the Instructions,

The appears in fair condition except the plank next the Waterway on the Starboard side and the main hatch Coming notice left to remove the plank no question but it has not been done

Committee Minute 14th July 1843

Character assigned Revised to F.1

Forutney
deferred
Notice to owner
14/7/43

No. ³⁵ 35 Survey held at London Date 11 July 1843
 on the Regia Master Spencer
 Tonnage 128 Built at Garnock When built 1839
 By whom built — Owners Silva
 Port belonging to London Destined Voyage Hambro
 If Surveyed Afloat or in Dry Dock afloat

Original Survey, No. 312 Port of Yarmouth, Lon 8673, 9157, Classed 9 A1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>do where seen</u>	Pumps <u>good</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>good</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>do</u>

General Observations and Opinion,
 as required by the Instructions,

Is in an efficient condition and may remain as classed

Committee Minute 14th July 1843

Character assigned 9 A1

Forutney



© 2019
 Lloyd's Register
 Foundation

When the has not had any Copper on the bottom the class