

ANNUAL SURVEYS.

9882

No. 1020 Survey held at London Date 14 June 1843
 on the BK "Commodore" Master B. Hore
 Tonnage 203 Built at Newport When built 1835
 By whom built _____ Owners H. Smith
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Shoos Dock

Original Survey, No. 1020 Port of Liverpool, Lon 1440, 5316, Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks	<u>Good</u>	Transoms	<u>Good</u>	Capstan	<u>Good</u>
Upper Deck Beams & Fastenings	<u>Sette</u>	Timbers of the Frame	<u>When Sea Sette</u>	Pumps	<u>Sette</u>
Lower Deck Beams & Fastenings	<u>Sette</u>	Topsides	<u>Sette</u>	Masts, Yards, &c.	<u>Sufficient</u>
Spirkettling	<u>Sette</u>	Wales	<u>Sette</u>	Sails	<u>Sette</u>
Plank Shears	<u>Sette</u>	Counter	<u>Sette</u>	Cables	<u>Sette</u>
Waterways	<u>Sette</u>	Plank and Treenails (Outside to the Water's Edge.)	<u>Sette</u>	Anchors No. of <u>3 Bowers 1 Stream</u>	
Hatchway Comings	<u>Sette</u>	Rudder	<u>Sette</u>	Standing & Running Rigging	<u>Sufficient</u>
Breasthooks	<u>Sette</u>	Windlass	<u>Sette</u>	<u>Yellow Metal Latches</u>	

General Observations and Opinion,
 as required by the Instructions,

as this vessel is in sound and efficient
 condition she may remain as Classed

Committee Minute 14th July 1843

Character assigned 12 A 1

Joseph H. Hatcher

Montenay

No. 57 Survey held at London Date 20th June 1843
 on the Ocean Queen Master Van Zuijlen
 Tonnage 737 Built at New Brunswick When built 1841
 By whom built _____ Owners Gardner & Co
 Port belonging to London Destined Voyage India Aden
 If Surveyed Afloat or in Dry Dock Fletcher's Dock

Original Survey, No. 9391 Port of London Classed 4 A 1

The Surveyor is required to state the present Condition of the

Decks	<u>Good</u>	Transoms	<u>Good</u>	Capstan	<u>Good</u>
Upper Deck Beams & Fastenings	<u>Sette</u>	Timbers of the Frame	<u>When Sea Good</u>	Pumps	<u>Sette</u>
Lower Deck Beams & Fastenings	<u>Sette</u>	Topsides	<u>Good</u>	Masts, Yards, &c.	<u>Sufficient</u>
Spirkettling	<u>Sette</u>	Wales	<u>Sette</u>	Sails	<u>Sette</u>
Plank Shears	<u>Sette</u>	Counter	<u>Sette</u>	Cables	<u>Sette</u>
Waterways	<u>Sette</u>	Plank and Treenails (Outside to the Water's Edge.)	<u>Sette</u>	Anchors No. of <u>3 Bowers 1 Stream</u>	
Hatchway Comings	<u>Sette</u>	Rudder	<u>Sette</u>	Standing & Running Rigging	<u>Sufficient</u>
Breasthooks	<u>Sette</u>	Windlass	<u>Sette</u>	<u>Yellow Metal Smooth & Good</u>	

General Observations and Opinion,
 as required by the Instructions,

The Wales had been sheathed with wood to the
 good water line, which was now Copper Nailed &
 the Rudder Coppered to the same height. And she
 is in good & efficient condition she may remain

Committee Minute 14th July 1843

Character assigned 4 A 1

Joseph H. Hatcher

Montenay