

# REPORT of SURVEY for REPAIRS.

9898  
H

No. 130 Survey held at London Date July 14<sup>th</sup> 1843  
 on the B<sup>d</sup> Deptford Master George Dedwith  
 Tonnage 107 Built at Barnmouth When built 1810  
 By whom built \_\_\_\_\_ Owners Dedwith  
 Port belonging to Barnmouth Destined Voyage Gabray  
 If Surveyed Afloat or in Dry Dock Lincolns Lane

Original Survey, No. 535 Dated 1842 Classed A.1

Port London, Nov 629, Lio 374, Lon 8899.  
 REPAIRS reported to be done at Bangor June 1843 - all new  
outside plank from the keel to the Bilge - and one  
strake out inside each side at the Bilge - new  
Windlass - Bitts, & Hale Bitt. - Stated to be cancelled  
throughout - Ironails new when the plank  
is shifted outside - Ceiling indifferent in places  
requires repair

## Present Condition of the

Decks <u>Light well worn</u>	Transoms <u>Not seen</u>	Windlass <u>New 1843</u>
Upper Deck Beams & Fastenings <u>fair</u>	Timbers of the Frame <u>good when seen</u>	Capstan _____
Lower Deck Beams & Fastenings _____	Topsides <u>Good</u>	Pumps <u>Good</u>
Spirkettling <u>Good</u>	Wales _____	Masts, Yards, &c. _____
Plank Shears _____	Counter _____	Sails <u>2 Sails - fair</u>
Waterways <u>new</u>	Plank & Treennails (Outside to the Water's Edge) _____	Cables <u>2 Chains - &amp; 3 Buntens</u>
Hatchway Comings <u>Good</u>	Rudder _____	Anchors No. of <u>2 . 1 . 2</u>
Breasthooks <u>Not seen</u>	Copper _____	Standing & Running Rigging <u>Good</u>

General Observations and Opinion, In my opinion this vessel is for the present  
eligible to remain as classed A.1

George Bayley

The Amount of Fee.....£ — : 10 : — is received by me, H

Committee's Minute 18<sup>th</sup> July 1843

Character assigned A.1 - new repairs



© 2019

Lloyd's Register  
Foundation

LON G15-0353