

## ANNUAL SURVEYS.

9932

No. 537 Survey held at London Date 15 July 1843  
 on the Brig "Delgrave" Master Donaldson  
 Tonnage 746 Built at Chester When built 1818  
 By whom built \_\_\_\_\_ Owners Wilson & Co  
 Port belonging to Worthington Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock New Crane Dock

Original Survey, No. 70,142 Port of LiverpoolClassed \*AE 1

The Surveyor is required to state the present Condition of the

Decks	<u>Good</u>	Transoms	<u>Good</u>	Capstan	
Upper Deck Beams & Fastenings	<u>Do</u>	Timbers of the Frame	<u>Not Seen</u>	Pumps	<u>Good</u>
Lower Deck Beams & Fastenings	<u>Do</u>	Topsides	<u>Good</u>	Masts, Yards, &c.	<u>Sufficient</u>
Spirkettling	<u>Do</u>	Wales	<u>Do</u>	Sails	<u>Do</u>
Plank Shears	<u>Do</u>	Counter	<u>Do</u>	Cables	<u>Do</u>
Waterways	<u>Do</u>	Plank and Treenails (Outside to the Water's Edge.)	<u>Do</u>	Anchors No. of	<u>21 1/2 1/2 1/2</u>
Hatchway Comings	<u>Do</u>	Rudder	<u>Do</u>	Standing & Running Rigging	<u>Do</u>
Breasthooks	<u>Do</u>	Windlass	<u>Do</u>	Copper	<u>Yellow Metal</u>

General Observations and Opinion,  
as required by the Instructions,

at this time her bottom was Caulked and  
 Sheathed with Yellow Metal on dry paper.

Committee Minute

1st August 1843

Remain as Classed.

Character assigned

AE 1 Antique Joseph H. Hatcher  
as Classed

No. 537 Survey held at London Date 15 July 1843  
 on the Bark "John Willis" Master John Willis  
 Tonnage 320 old 366 new Built at Sunderland When built 1839  
 By whom built \_\_\_\_\_ Owners Willis & Co  
 Port belonging to London Destined Voyage Demerara  
 If Surveyed Afloat or in Dry Dock New Crane Dock

Original Survey, No. 1466 Port of SunderlandClassed 10 A 1

The Surveyor is required to state the present Condition of the

Decks	<u>Good</u>	Transoms	<u>Good</u>	Capstan	<u>Good</u>
Upper Deck Beams & Fastenings	<u>Do</u>	Timbers of the Frame	<u>Not Seen</u>	Pumps	<u>Do</u>
Lower Deck Beams & Fastenings	<u>Do</u>	Topsides	<u>Good</u>	Masts, Yards, &c.	<u>Sufficient</u>
Spirkettling	<u>Do</u>	Wales	<u>Do</u>	Sails	<u>Do</u>
Plank Shears	<u>Do</u>	Counter	<u>Do</u>	Cables	<u>Do</u>
Waterways	<u>Do</u>	Plank and Treenails (Outside to the Water's Edge.)	<u>Do</u>	Anchors No. of	<u>Do</u>
Hatchway Comings	<u>Do</u>	Rudder	<u>Do</u>	Standing & Running Rigging	<u>Do</u>
Breasthooks	<u>Do</u>	Windlass	<u>Do</u>	Copper	<u>Yellow Metal</u>

General Observations and Opinion,  
as required by the Instructions,

at this time she was docked to inspect the  
 state of the bottom & had a new fore piece  
 of false keel fitted. She is in good and

Committee Minute

1st August 1843

Sufficient Condition and may remain

Character assigned

10 A 1 as Classed Joseph H. Hatcher  
as Classed