

# REPORT of SURVEY for REPAIRS.

*Change of Owners*

10,074

No. *11* Survey held at *London* Date *Sept 21* 184*3*  
 In the *St Wrobin* Master *J Pothey*  
 Tonnage *166* Built at *Shroton* When built *1837*  
 By whom built *—* Owners *Pothey*  
 Port belonging to *London* Destined Voyage *Mediterranean*  
 Surveyed Afloat or in Dry Dock *West India Dock*

Original Survey, No. *8776* Dated *—* Classed *12 A 1*

Port *London*

REPAIRS *Caution from the Copper work of the keels examined*

## Present Condition of the

Decks	Transoms <i>good</i>	Windlass <i>good</i>
Upper Deck Beams & Fastenings	Timbers of the Frame <i>sound where seen</i>	Capstan <i>"</i>
Lower Deck Beams & Fastenings	Topsides <i>good</i>	Pumps <i>"</i>
Spirkettling	Wales <i>"</i>	Masts, Yards, &c. <i>"</i>
Plank Shears	Counter <i>"</i>	Sails <i>Not found</i>
Waterways	Plank & Treenails <i>"</i> (Outside to the Water's Edge)	Cables <i>"</i>
Hatchway Comings	Rudder <i>"</i>	Anchors No. of <i>"</i>
Breasthooks	Copper <i>"</i>	Standing & Running Rigging <i>good</i>

General Observations and Opinion, *Is in a very good & efficient state to retain her present class*

*Wm. P. Pothey*

The Amount of Fee.....£ *1* : — : — is received by me, *LR*

Committee's Minute *26th September 1843*

Character assigned *12 A 1*

*LR*



© 2019

Lloyd's Register  
Foundation

LN616-0057