

No. 207 Survey held at London Date Oct 3rd 1843
on the Bk Jane Lockhart Master Cofford
Tonnage 250 Built at Sunderland When built 1820
By whom built _____ Owners Salisbury
Port belonging to Dominica Destined Voyage Dominica
If Surveyed Afloat or in Dry Dock Simkins Dock

10,151

Original Survey, No. 9234 Port of London

Classed A, 1

Ant 37-3

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>//</u>	Timbers of the Frame <u>sound & heavy</u>	Pumps <u>//</u>
Lower Deck Beams & Fastenings <u>//</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>//</u>
Spirketting <u>Good</u>	Wales <u>//</u>	Sails <u>Well found</u>
Plank Shears <u>//</u>	Counter <u>//</u>	Cables <u>//</u>
Waterways <u>//</u>	Plank and Treenails <u>Good</u> (Outside to the Water's Edge.)	Anchors No. of <u>Good</u>
Hatchway Comings <u>//</u>	Rudder <u>//</u>	Standing & Running Rigging <u>//</u>
Breasthooks <u>//</u>	Windlass <u>//</u>	Copper <u>//</u>

General Observations and Opinion, Bottom caulked & coppered over paper and wear of union
as required by the Instructions, from her general good condition she is fit for the safe

Upper crane & sheath in conveyance of dry & perishable cargoes to & from all
parts of the World and may be classed A, 1
No 1039 with the Asterisk

Committee Minute 20th October 1843

Character assigned A, 1 Asterisk

Record copied by George Bayley

No. 28 Survey held at London Date October 8th 1843
on the Bk Ralph Bernal Master Bridges
Tonnage 314 Built at Sunderland When built 1835
By whom built _____ Owners Macham & Co
Port belonging to London Destined Voyage Jamaica
If Surveyed Afloat or in Dry Dock Duke's Dock

Original Survey, No. 8703 Port of London May 1842 Classed 10A1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirketting	Wales	Sails <u>Good & efficient</u>
Plank Shears <u>Good</u>	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper <u>up 1843</u>

General Observations and Opinion, Repaired copper - In my opinion she is eligible
as required by the Instructions, to remain as classed 10A1

Committee Minute 20th October 1843

Character assigned 10A1



© 2019

Lloyd's Register
Foundation