

ANNUAL SURVEYS.

10.100
JH

No. 220 Survey held at London Date Oct 24 1843
 on the Bk Hector Master Stee
 Tonnage 243 Built at Bristol When built 1824
 By whom built _____ Owners Jeyn & Co
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 9253 Port of London 1842 Continued Rest. 35-7 Jey Classed A 1 two years

The Surveyor is required to state the present Condition of the

Decks	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings	Timbers of the Frame <u>sound & house</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings	Topsides <u>Good</u>	Masts, Yards, &c. _____
Spirketting	Wales <u>"</u>	Sails <u>Wet & frayed</u>
Plank Shears <u>Good</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways	Plank and Treenails (Outside to the Water's Edge.) <u>"</u>	Anchors No. of <u>"</u>
Hatchway Comings	Rudder <u>"</u>	Standing & Running Rigging <u>good</u>
Breasthooks	Windlass <u>"</u>	Copper <u>on 1842</u>

General Observations and Opinion, Is throughout in a very efficient & retain her
 as required by the Instructions, present shape

Math. P. Wood

Committee Minute 24th October 1843

Character assigned Class 2 A 1

No. 410 Survey held at London Date Oct 18 1843
 on the Bk Ensign Master Slader
 Tonnage 300 Built at Peterhead When built 1826
 By whom built _____ Owners J. Thomas
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock West India Dock

Original Survey, No. 9184 Port of London Classed A. 1 Potwick

The Surveyor is required to state the present Condition of the


Decks	Transoms <u>Sound</u>	Capstan _____
Upper Deck Beams & Fastenings	Timbers of the Frame <u>sound & house</u>	Pumps _____
Lower Deck Beams & Fastenings	Topsides <u>Good</u>	Masts, Yards, &c. _____
Spirketting	Wales <u>"</u>	Sails _____
Plank Shears <u>Good</u>	Counter <u>"</u>	Cables _____
Waterways	Plank and Treenails (Outside to the Water's Edge.) <u>"</u>	Anchors No. of _____
Hatchway Comings	Rudder <u>"</u>	Standing & Running Rigging _____
Breasthooks	Windlass <u>"</u>	Copper <u>Yellow Metal 1841</u>

General Observations and Opinion, From her general good appearance I am of opinion
 as required by the Instructions, she is fit for the safe conveyance of men & goods to & from all parts of all the West India
Island & may retain her present shape A. 1 with the

Committee Minute 24th October 1843

Character assigned A. 1 asterisk

Math. P. Wood



LON 616-0152