

REPORT of SURVEY for REPAIRS.

10.198

No. 96 Survey held at London Date Nov 14 3 1843
 on the Bk Pathfinder Master J Burtin
 Tonnage 316 Built at Sunderland When built 1841
 By whom built _____ Owners Lewis & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Fletcher's Dock

Original Survey, No. 7761 Dated 1 Classed PA1

Port of London

REPAIRS Ship's, a listing cut out of the hooded end of keel seam of the sheathing, Wales and upperworks caulked and sheathed with Yellow Metal.

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, Is in a very good & efficient state and may continue in her present class

Wm. H. Piddleton
J. H. Piddleton

The Amount of Fee.....£ : : is received by me,

Committee's Minute 10th November 1843

Character assigned 8 1/2 shd



© 2019

Lloyd's Register Foundation

9810-0186