

# ANNUAL SURVEYS.

10,281

No. 63 Survey held at London Date Dec 1 1843  
 on the Bk Emma Master White  
 Tonnage 378 Built at Shields When built 1836 1837  
 By whom built Edwards Owners Edwards  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Carters Dock

Original Survey, No. 10242 Port of Shields Jan 9 1842 Classed SA 1  
London

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

*Good* *Good* *Good and efficient*  
Ym 1843

General Observations and Opinion, Shipped. hung & caulked to rule - sheathed with yellow metal  
 as required by the Instructions, on paper to the rule - Three planks shifted in the topside on  
the Larboard Bow - In my opinion she is eligible to remain  
as classed SA 1

Committee Minute 12th December 1843

Character assigned

George Bayley

Nathaniel Wood

No. 65 Survey held at \_\_\_\_\_ Date Dec 24, 5 1843  
 on the Bk Waterwitch Master Douglas  
 Tonnage 253 Built at Pembroke When built 1820  
 By whom built R M Cockyard Owners Winton  
 Port belonging to London Destined Voyage Mauritius  
 If Surveyed Afloat or in Dry Dock Fletchers Dock

Original Survey, No. 5951 Port of London 1839 Classed SA 1  
1839. 8 years

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

*Good* *Good* *Good*  
Watt found  
3 Bp 1 Str 1 Hodge  
good  
Ym 1843

General Observations and Opinion, has been done in Sydney and some repairs done to bottom  
 as required by the Instructions, now shipped. Caulked bulwarks and sheathed with yellow metal  
In our opinion she is eligible to remain as classed SA 1

Committee Minute 12th December 1843

Character assigned

George Bayley

Nathaniel Wood