

ANNUAL SURVEYS.

No. 245 Survey held at London Date Feb 17 1844
 on the Bk Wiza Master Barker
 Tonnage 313 Built at Nova Scotia When built 1841
 By whom built _____ Owners Tristram
 Port belonging to St Vincent Destined Voyage St Vincent
 If Surveyed Afloat or in Dry Dock West India Dock

Original Survey, No. 8255 Port of London

Classed 4A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Standard</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>good</u>
Spirkettling <u>Good</u>	Wales <u>"</u>	Sails <u>Well found</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>good</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>"</u>

General Observations and Opinion, Presents a very firm appearance and is in an efficient state
 as required by the Instructions, both in the hull & stores to remain as classed
at the present time. caulked above the upper

Committee Minute 20th Feb 1844

Character assigned 4A1

No. 34 Survey held at London Date Feb 17 1844
 on the Bk Barbara Gordon Master A Richie
 Tonnage 330 Built at Switzerland When built 1836
 By whom built _____ Owners Gordon & Co
 Port belonging to London Destined Voyage Chicago
 If Surveyed Afloat or in Dry Dock West India Dock

Original Survey, No. 9919 Port of London

Classed 11A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Standard</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Sails <u>Well found</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>as 1841</u>

General Observations and Opinion, Appears in all respects in a good & efficient state to
 as required by the Instructions, continue as classed

Committee Minute 20th February 1844

Character assigned 11A1



© 2019

Lloyd's Register
Foundation