

# ANNUAL SURVEYS.

10.4/4

No. 213 Survey held at London Date 24 July 1844  
 on the M Florence Master Davis  
 Tonnage 179 Built at Furnouth When built 1829  
 By whom built — Owners Pied Co  
 Port belonging to London Destined Voyage Madura  
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 10276 Port of London

Classed 4A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>—</u>
Upper Deck Beams & Fastenings <u>Firm</u>	Timbers of the Frame <u>do</u>	Pumps <u>Good &amp; Sufficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>do</u>	Masts, Yards, &c. <u>do do</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Sails <u>do do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do do</u>
Waterways <u>do</u>	Plank and Treenails (Outside to the Water's Edge.) <u>do</u>	Anchors No. of <u>do do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>—</u>

General Observations and Opinion,

as required by the Instructions, Is in an efficient condition and may remain as classed

Committee Minute 15th March 1844

Character assigned 4A1

No. 220 Survey held at London Date 1 March 1844  
 on the Chr Menor Master Wickham  
 Tonnage 147 Built at St Island When built 1842  
 By whom built — Owners Canvass  
 Port belonging to London Destined Voyage Lyall  
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 5446 Port of Liverpool

Classed 4A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>—</u>
Upper Deck Beams & Fastenings <u>Firm</u>	Timbers of the Frame <u>do</u>	Pumps <u>efficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>do</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails (Outside to the Water's Edge.) <u>do</u>	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>Good</u>

General Observations and Opinion,

as required by the Instructions, Appears in an efficient state and may remain as classed

Committee Minute 15th March 1844

Character assigned 4A1



© 2019

Lloyd's Register Foundation

LONG 16-0472