

## ANNUAL SURVEYS.

10,515

No. 276 Survey held at London Date 14<sup>th</sup> 22 March 1844  
 on the Albin Master Scott  
 Tonnage 328 Built at Aston When built 1828  
 By whom built - Owners Hutchinson  
 Port belonging to London Destined Voyage Hambro  
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 352 Port of Hockton Classed 10.7.1

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms <u>good</u>	Capstan <u>-</u>
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>as when new</u>	Pumps <u>efficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>good</u>	Masts, Yards, &c. <u>do</u>
Spirketting <u>good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u> <u>new</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>-</u>

General Observations and Opinion,

as required by the Instructions, He appears in an efficient condition for the conveyance of dry and perishable Cargos to & from all parts of the world and may remain as a rapid & comfortable  
 Committee Minute 26<sup>th</sup> March 1844

Character assigned Ex. 1 asterisk L.P.

No. 568 Survey held at London Date 22 March 1844  
 on the Albion Master Foster  
 Tonnage 402 Built at Newcastle When built 1825  
 By whom built - Owners Burton  
 Port belonging to Liverpool Destined Voyage India  
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 4697 Port of Liverpool Classed 10.7.1

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms <u>good</u>	Capstan <u>-</u>
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>as when new</u>	Pumps <u>efficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>good</u>	Masts, Yards, &c. <u>do</u>
Spirketting <u>good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>do</u> <u>1842</u>

General Observations and Opinion,

as required by the Instructions, Two additional knees put to the Hold Beams and the ship appears in good and efficient condition for the conveyance of dry and perishable Cargos to & from all parts of the world and may remain as a rapid & comfortable  
 Committee Minute 26<sup>th</sup> March 1844  
 Character assigned Ex. 1 asterisk L.P.