

REPORT of SURVEY for REPAIRS.

Charge of Owners
No. 134 Survey held at London Date April 26 1844
on the Bk Margaret Master H. Croft
Tonnage 312 Built at Quebec When built 1824
By whom built _____ Owners Dowell & Co
Port belonging to London x Destined Voyage Quebec
If Surveyed Afloat or in Dry Dock on the Mays

Last Survey, No. 10001 Classed _____

Port London

REPAIRS Bottom examined & bolts caulked

Notice sent to Gen agreeably to the Rule Page 18 Sect 63

Present Condition of the

Decks <u>Indifferent</u>	Transoms <u>not seen</u>	Windlass _____
Upper Deck Beams & Fastenings <u>works</u>	Timbers of the Frame <u>defective in place</u>	Capstan _____
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Indifferent</u>	Pumps _____
Spirkettling <u>Indifferent</u>	Wales <u>fair</u>	Masts, Yards, &c. <u>good</u>
Plank Shears _____	Counter _____	Sails <u>of</u>
Waterways _____	Plank & Treenails (Outside to the Water's Edge) <u>good</u>	Cables <u>sufficient</u>
Hatchway Comings _____	Rudder _____	Anchors No. of _____
Breasthooks <u>not seen</u>	Copper _____	Standing & Running Rigging _____

General Observations and Opinion. some of the hold beams defective and from their general appearance I am of opinion she is not entitled to any Class

[Signature]

The Amount of Fee £ : : is received by me,

Committee's Minute 3rd May 1844

Character assigned _____



© 2019

Lloyd's Register
Foundation

LON 617-0138