

## ANNUAL SURVEYS.

Rec<sup>d</sup> 13 May

10. 1834

No. 12 Survey held at London Date May 10<sup>th</sup> 1844  
 on the Bk. Caleb Angas Master Whittle 27  
 Tonnage 304 Built at Shilds When built 1829  
 By whom built \_\_\_\_\_ Owners C. J. Angas  
 Port belonging to London Destined Voyage Honduras  
 If Surveyed Afloat or in Dry Dock West India Dock

Last Survey, No. 9479 Port of LondonClassed 10 A. 1  
 Coult. 40 3

The Surveyor is required to state the present Condition of the

Decks <u>in condition</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u>sound &amp; otherwise</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>good</u>
Spirketting <u>Good</u>	Wales <u>"</u>	Sails <u>Well found</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>in condition</u>	Plank and Treennails <u>Good</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings <u>Good</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>Yellow Metal</u>

General Observations and Opinion, At the present time on the Brake Deck from the Main rigging  
 as required by the Instructions, after new plank shears, shear stake & waterway, the timbers  
where exposed very sound & I am of opinion to fit for the safe  
conveyance of dry & perishable cargoes and may be

Committee Minute 14<sup>th</sup> May 1844Character assigned A. 1

No. 57 Survey held at London Date May 1844  
 on the Ship Camilla Master Canney  
 Tonnage 303 Built at Newcastle When built 1829  
 By whom built \_\_\_\_\_ Owners Burton & Co  
 Port belonging to London Destined Voyage Jamaica  
 If Surveyed Afloat or in Dry Dock Plutcher Dock

Last Survey, No. 9909 Port of LondonClassed 12 A. 1  
 Coult. 41 4

The Surveyor is required to state the present Condition of the

Decks _____	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings _____	Timbers of the Frame <u>sound &amp; otherwise</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings _____	Topsides <u>Good</u>	Masts, Yards, &c. <u>good</u>
Spirketting _____	Wales <u>"</u>	Sails <u>"</u>
Plank Shears <u>Good</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways _____	Plank and Treennails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings _____	Rudder <u>"</u>	Standing & Running Rigging <u>good</u>
Breasthooks _____	Windlass <u>"</u>	Copper <u>in 1843</u>

General Observations and Opinion, Head & cutwater taken down & refitted & partially caulked  
 as required by the Instructions, and from her general good appearance may retain her  
her present character

Committee Minute 14<sup>th</sup> May 1844Character assigned and?

© 2019

Lloyd's Register  
Foundation