

REPORT of SURVEY for REPAIRS.

& Change of Owners

10.642

Rec^d 11 May

No. 5 Survey held at London Date May 6 184 4
 on the Bk Manchester Master John Carphin
 Tonnage 283 Built at Sunderland When built 1843 Registered 1844 Register produced
 By whom built J. Hull Owners Mitcheson
 Port belonging to London Destined Voyage Assension &aney
 If Surveyed Afloat or in Dry Dock Savender Dock

Last Survey, No. 2389 Not Classed

Port Sunderland

REPAIRS Caulked from the keel overale and sheathed with Yellow Metal

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettig	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors
Breasthooks	<u>Yellow Metal May 1844</u>	No. of <u>3 Bows 1 Stm 2 Hedges</u>
		Standing & Running Rigging

General Observations and Opinion, Is in a very good & efficient state to retain her present class

The Amount of Fee.....£ 3 : - : - is received by me, H

Committee's Minute 17th May 1844

Character assigned A 1 for 5 years



© 2019

Lloyd's Register Foundation

LON 617-0169