

REPORT of SURVEY for REPAIRS.

No. _____ Survey held at London Date Oct 14. 19th 1843
 on the B^t Ethelred Master Lawrence W. Bradford
 Tonnage 399 Built at London When built 1811
 By whom built Palmer Owners J. Hamilton
 Port belonging to London Destined Voyage Jamaica Africa
 If Surveyed Afloat or in Dry Dock West India Dock

Original Survey, No. _____ Dated Feb 7 1843 Classed A. 1

Port London std with standards (5)
 REPAIRS At the present time new upper deck waterways - several beams
scuppers - plank near the Waterway several new hogging
knives and upperworks caulked

at m notes to 18.28 Oct

Present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Windlass <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>sound & house</u>	Capstan <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Pumps <u>"</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Masts, Yards, &c. <u>"</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Sails <u>Well found</u>
Waterways <u>"</u>	Plank & Treenails (Outside to the Water's Edge) <u>"</u>	Cables <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Anchors No. of <u>"</u>
Breasthooks <u>"</u>	Copper <u>2y over on hull</u>	Standing & Running Rigging <u>good</u>

General Observations and Opinion,

The timbers where exposed sound & from her general good condition we are of opinion she is fit for the safe conveyance of dry & perishable cargoes to & from all parts of the World and may be continued A. 1 with the Assent

The Amount of Fee.....£ : : is received by me,

Committee's Minute _____ 18 _____

Character assigned _____



© 2019

Lloyd's Register
Foundation

LON 617-0193