

REPORT of SURVEY for REPAIRS. and Change of Owners

10,733

No. 35 Survey held at London Date 25 May 1844
on the Brig "James" Master R Henderson
Tonnage 193 Built at Perth When built 1840
By whom built _____ Owners R Henderson
Port belonging to Glasgow Destined Voyage G. Y. Hope
If Surveyed Afloat or in Dry Dock in Gun Dock

Last Survey, No. 6777 Classed 5 A 1
Port London

REPAIRS

at present the thick strake below the bores and several
parts of the upper Courses ^{and one plank of bottom} was slightly wormed which has
been repaired and the Copper raised one sheet higher.
The false keel that was much wormed has been removed
and she remains without a false keel - the Copper
of bottom has been patched -

Present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Windlass <u>Good</u>
Upper Deck Beams & Fastenings <u>—</u>	Timbers of the Frame <u>Not seen</u>	Capstan <u>—</u>
Lower Deck Beams & Fastenings <u>—</u>	Topsides <u>Good</u>	Pumps <u>overhauled</u>
Spirketting <u>—</u>	Wales <u>—</u>	Masts, Yards, &c. <u>Sufficient</u>
Plank Shears <u>—</u>	Counter <u>—</u>	Sails <u>—</u>
Waterways <u>—</u>	Plank & Treenails (Outside to the Water's Edge) <u>—</u>	Cables <u>—</u>
Hatchway Comings <u>—</u>	Rudder <u>—</u>	Anchors No. of <u>2 B 1st 1 1/2</u>
Breasthooks <u>—</u>	Copper <u>patched</u>	Standing & Running Rigging <u>Good</u>

General Observations and Opinion,

This Vessel appears in efficient Condition
and may remain as Classed -
J. H. H. H.

The Amount of Fee.....£ 1 : — : — is received by me, A

Committee's Minute 7th June 1844

Character assigned 5 A 1 very repair



© 2019

Lloyd's Register
Foundation

LON 617-0266