

REPORT of SURVEY for REPAIRS.

Change of Property No. 7110

No. 387 Survey held at London Date June 9 184 4
 on the MS Durango Master Parker
 Tonnage 300 Built at New Brunswick When built 1841
 By whom built _____ Owners _____
 Port belonging to London Destined Voyage Harbottle Upricer
 If Surveyed Afloat or in Dry Dock Afloat Del 5

Last Survey, No. 4720 Classed 5 A 1
 Port Liverpool

REPAIRS

See for men uproot

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,

This vessel has not been at sea since last reported
Is in efficient condition and may remain
as Classed -

The Amount of Fee.....£ 2 : - : - is received by me. H. H. H.

Committee's Minute 11th June 18 44

Character assigned 5 A 1 renewed

MS Harbottle by Col. Ross
Commercial Port



© 2019

Lloyd's Register
 Foundation

LON 617-0273