

ANNUAL SURVEYS.

10.755

LA

No. 180 on the Sh Diamond Survey held at London Date June 13 1844
 Tonnage 115 Built at Stonehouse Plymouth When built 1815
 By whom built 94 Owners Clark & Co
 Port belonging to Plymouth Destined Voyage Plymouth
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 9006 Port of London Classed A.1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>as when seen</u>	Pumps <u>Efficient</u>
Lower Deck Beams & Fastenings <u>—</u>	Topsides <u>in fair condition</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>Good</u>	Wales <u>do do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do do</u>	Cables <u>do</u>
Waterways <u>fair</u>	Plank and Treenails <u>do do</u> <small>(Outside to the Water's Edge.)</small>	Anchors No. of <u>do</u>
Hatchway Comings <u>Good</u>	Rudder <u>Good</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper

General Observations and Opinion,
 as required by the Instructions, Very well & remarkably well built
 vessel now in very fair condition for the conveyance
 of dry and perishable Cargoes and may be
 Committee Minute 18th June 1844 as classed
 Character assigned A.1 Hourtney

No. 572 on the Sh Mary Anne Survey held at London Date June 11 1844
 Tonnage 290 Built at Sunderland When built 1834
 By whom built — Owners Spinks
 Port belonging to Sunderland Destined Voyage Zaire
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 9100 Port of London Classed C.3.1
Cont 42 - 3 Jrs

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>do</u>	Pumps <u>Efficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>do</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> <small>(Outside to the Water's Edge.)</small>	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>4 1/2 tons</u>

General Observations and Opinion,
 as required by the Instructions, Is in an efficient condition and may
 be used as classed
 Committee Minute 18th June 1844 as classed
 Character assigned C.3.1 Hourtney

