

REPORT of SURVEY for REPAIRS.

10.765

No. 43 Survey held at London Date June 7th to 17th 1844
 on the Bk Earl Grey Master Melison
 Tonnage 571 Built at Newcastle When built 1835
 By whom built _____ Owners D Damber
 Port belonging to London Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Curling & Youngs Dock

Last Survey, No. 10576 Classed 10 A 1
 Port London

REPAIRS Having been on shore on the Gardner sand has been stripped
hull, bottom caulked, six pairs of knee under the side beams
and sheathed with yellow metal over felt.

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Screw	Standing & Running Rigging

General Observations and Opinion This vessel appears in all respects fit to
retain her present Class

R. M. D. L.
T. H. L. L.

The Amount of Fee £ : : is received by me,

Committee's Minute 21st June 1844

Character assigned 10 A 1 revised
Special 4.4.0



© 2019

Lloyd's Register
 Foundation

LON 617-0299