

# REPORT of SURVEY for REPAIRS.

10.777  
Recd 25

No. 400 Survey held at Sunder Date January 1844  
on the Bk Lord Auckland Master Brown  
Tonnage 576 00 Built at Calcutta When built 1836  
628 New  
By whom built \_\_\_\_\_ Owners Brown & Co  
Port belonging to Sunder Destined Voyage Sydney  
If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 7856 Classed 12 A1

Port Sunder

REPAIRS At Calcutta in Feb'y 1843 bottom shipped, caulked from the  
keel overall, and sheathed with inch fir over Gulgul & Copper  
over Gulgul  
At the present time having been on shore in the Phoenix  
new fore gripe, the fore body shipped & caulked, & as sheathed  
and Coppered from the after part of the fore channel forward

## Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, Is throughout in a very efficient state  
As retain her present character

*W. H. Brown*

The Amount of Fee.....£ 3 : - : - is received by me, *W. H. Brown*

Committee's Minute 28th June 1844

Character assigned 12 A1 *W. H. Brown*



© 2019

Lloyd's Register  
Foundation