

ANNUAL SURVEYS.

10903

No. 548 Survey held at London Date July 25 1844
 on the Bk Providence Master H. Hicks
 Tonnage 200 Built at Worshipam When built 1840
 By whom built _____ Owners Popham
 Port belonging to Exeter Destined Voyage Halifax
 If Surveyed Afloat or in Dry Dock Bullhead dock

Last Survey, No. 334 Port of London Classed 12A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Good</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Sails <u>Well found</u>
Plank Shears <u>Good</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails (Outside to the Water's Edge.) <u>"</u>	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	<u>Copper</u> <u>Yellow Metal over paper</u>

General Observations and Opinion, Whipped, caulked & sheathed with yellow metal over
 as required by the Instructions, paper and appears in all respects in an efficient
condition to retain her present shape

Committee Minute 9th August 1844

Character assigned 12A1 Rec'd Mr.

No. 447 Survey held at London Date August 7 1844
 on the Bk Woodland Castle Master Williams
 Tonnage 160 Built at Yarmouth When built 1802
 By whom built _____ Owners Reid & Co
 Port belonging to Cork Destined Voyage Riga
 If Surveyed Afloat or in Dry Dock on the ways

Last Survey, No. 325 Port of Cork Classed A.1

The Surveyor is required to state the present Condition of the

Decks <u>Indifferent</u>	Transoms <u>not seen</u>	Capstan _____
Upper Deck Beams & Fastenings <u>Defective</u>	Timbers of the Frame _____	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Indifferent</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>Moderate</u>	Wales <u>"</u>	Sails <u>"</u>
Plank Shears <u>Indifferent</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails (Outside to the Water's Edge.) <u>"</u>	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>good</u>	Standing & Running Rigging <u>good</u>
Breasthooks <u>not seen</u>	Windlass _____	<u>Copper</u>

General Observations and Opinion, The shearstrokes are defective round the bolts
 as required by the Instructions, Ceiling much decayed, works at the upper & lower
Deck beams and from her general condition I am
of opinion she is only fit for the conveyance on short
voyages or if carried in their nature not subject to
sea damage and should be classed

Committee Minute 16th August 1844

Character assigned Reduced to I.1