

ANNUAL SURVEYS.

10973
Page 4 of 4

No. 108 on the *Bk Lady Sale* Survey held at *London* Date *August 31st Sep^r 1844*
 Tonnage *316* Built at *Newcastle* Master *W. Dillay*
 By whom built _____ When built *1843*
 Port belonging to *Shields* Owners *Shakers*
 If Surveyed Afloat or in Dry Dock *Free & aft Dock* Destined Voyage *Bermuda*

Last Survey, No. *2089* Port of *Newcastle* Classed *GA1*

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, *Bottom caulked & sheathed with yellow metal to the light mark - and appears in an efficient state to retain her present class -*

Committee Minute *6th September 1844*

Character assigned *GA1*

No. 233 on the *Sr Helen* Survey held at *London* Date *August 31 1844*
 Tonnage *132* Built at *Leith* Master *C. Currie*
 By whom built _____ When built *1841*
 Port belonging to *Hirkaldy* Owners *Currie*
 If Surveyed Afloat or in Dry Dock *on the ways* Destined Voyage *Syria*

Last Survey, No. *906y* Port of *London* Classed *GA1*

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, *Bottom examined and appears in all respects in an efficient condition to continue as classed*

Committee Minute *6th September 1844*

Character assigned *GA1*