

# REPORT of SURVEY for REPAIRS.

*Change of Owners*

11049

*Res 10 Oct 44*

No. *472* Survey held at *London* Date *Oct 8<sup>th</sup>* 1844

on the *Sr Princess Alice* Master *W. Cumming*

Tonnage *142* Built at *Christchurch* When built *1843*

By whom built \_\_\_\_\_ Owners *Cox & Co*

Port belonging to *London* Destined Voyage *Malta*

If Surveyed Afloat or in Dry Dock *London Dock*

Last Survey, No. *171* Classed *7A1*

Port *of Port*

REPAIRS *Caulked from the keel over all & sheathed with yellow metal over paper*

## Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c. <i>Good</i>
Plank Shears	Counter	Sails <i>Sufficient</i>
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	<i>Copper yellow metal over paper</i>	Standing & Running Rigging

General Observations and Opinion *This vessel is in a very good & efficient condition and appears in all respects with the exception of the treenails being Red Pine eligible to remain as classed*

The Amount of Fee £ *10* is received by me, *shop*

Committee's Minute *15<sup>th</sup> Oct 1844*

Character assigned *7A1*



© 2019  
Lloyd's Register  
Foundation  
LON 618 - 0060