

REPORT of SURVEY for REPAIRS.

No. _____ Survey held at London Date June 11 & 12 1844
 on the By Aphrodite Master A. Baillie
 Tonnage 270 Built at Bermuda When built 1826
 By whom built _____ Owners Switzerland
 Port belonging to St Vincent Destined Voyage St Vincent
 If Surveyed Afloat or in Dry Dock Cable Dock

Last Survey, No. _____ Classed A, 1 Westerly
 Port London

REPAIRS Having been on shore on the Goodwin Sand, the copper has been
stripped off, vessel hung in shrou, caulked to the upper
part of the plates and coppered over felt

An additional pair of staps standard to the main hatch beam

Present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Windlass _____
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound</u>	Capstan _____
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Pumps _____
Spirketting <u>Good</u>	Wales <u>"</u>	Masts, Yards, &c. <u>Good</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Sails <u>"</u>
Waterways <u>"</u>	Plank & Treenails (Outside to the Water's Edge) <u>"</u>	Cables <u>Sufficient</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Anchors No. of _____
Breasthooks <u>"</u>	Copper <u>June 1844</u>	Standing & Running Rigging _____

General Observations and Opinion,

From the good & efficient state of this vessel I am of
opinion she is fit for the safe conveyance of dry &
perishable cargoes to & from all parts of the world
and may retain her present class A, 1 with the notation

At Home 3/6

The Amount of Fee.....£ : : is received by me,

Committee's Minute _____ 18

Character assigned _____

Special L4, 4.0 p.

See Report, attached
dated 30 Oct.



© 2019

Lloyd's Register
Foundation

LON 618 - 0071