

ANNUAL SURVEYS.

11077

Revised
JH

No. 52 Survey held at London Date Oct 10th 1844
on the Bg Nauticus Master Gibson
Tonnage 232 Built at Scilly When built 1840
By whom built _____ Owners Hoskins
Port belonging to Scilly Destined Voyage Mauritius
If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 4763 Port of Swanport Classed 12A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan _____
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound where seen</u>	Pumps _____
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. _____
Spirkettling <u>Good</u>	Wales <u>"</u>	Sails <u>Well</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>Sound</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of _____
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging _____
Breasthooks <u>"</u>	Windlass _____	Copper _____

General Observations and Opinion, Bottom caulked & sheathed with yellow metal
as required by the Instructions, and is in the aspects in a good & efficient state

Committee Minute 22 October 1844

Character assigned 12A1 Record YP
ALB

W. H. L. M.

No. 280 Survey held at London Date Oct 19th 1844
on the Sr Liberator Master Elliot
Tonnage 125 Built at Waterford When built 1833
By whom built _____ Owners Angel & Co
Port belonging to Waterford Destined Voyage Waterford
If Surveyed Afloat or in Dry Dock on the ways

Last Survey, No. 100 Port of Waterford Classed 12A1

The Surveyor is required to state the present Condition of the

Decks _____	Transoms <u>Sound</u>	Capstan _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame <u>Sound where seen</u>	Pumps _____
Lower Deck Beams & Fastenings _____	Topsides <u>Good</u>	Masts, Yards, &c. _____
Spirkettling _____	Wales <u>"</u>	Sails _____
Plank Shears <u>Good</u>	Counter <u>"</u>	Cables _____
Waterways _____	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of _____
Hatchway Comings _____	Rudder <u>"</u>	Standing & Running Rigging _____
Breasthooks _____	Windlass <u>"</u>	Copper _____

General Observations and Opinion, Bottom caulked, one new plank in brass sheathed
as required by the Instructions, having been stove, and is throughout in an efficient
state to continue as classed

Committee Minute 22 October 1844

Character assigned 12A1 ALB

W. H. L. M.
© 2019
Lloyd's Register
Foundation