

REPORT of SURVEY for REPAIRS.

Change of Owners

11090

Ref 24002

No. 102 Survey held at London Date Oct 21 1844

on the Str Dee Master _____

Tonnage 127 Built at Ipswich When built 1828

By whom built _____ Owners London Waterfront Co

Port belonging to London Destined Voyage Coastways

If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 9212 Classed ¹² A.1

Port London

REPAIRS In September last on the starboard side nine new first foothooks, new bilge planks on both sides and new ceiling in the flat of American elm, bilges through bolted and caulked from the keel overall

Present Condition of the		
Decks <u>Good</u>	Transoms <u>Sound</u>	Windlass _____
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound & true</u>	Capstan _____
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Pumps _____
Spirkettling <u>Good</u>	Wales <u>"</u>	Masts, Yards, &c. <u>Good</u>
Plank Shears & Shear stake, fair	Counter <u>"</u>	Sails _____
Waterways <u>"</u>	Plank and Treennails <u>Fair</u>	Cables <u>Sufficient</u>
Hatchway Comings <u>"</u>	(Outside to the Water's Edge)	Anchors No. of _____
Breasthooks <u>Sound</u>	Rudder <u>Good</u>	Standing & Running Rigging _____
	Copper _____	

General Observations and Opinion, I am of opinion this vessel is in a good condition for the safe conveyance of dry & perishable cargoes and may continue as classed A.1

The Amount of Fee.....£ — : 10 : — is received by me, *AF*

Committee's Minute 25 Nov 18 44

Character assigned A.1



© 2019

Lloyd's Register Foundation

LCN 618-0103