

REPORT of SURVEY for REPAIRS.

No. 504 Survey held at London Date Nov 23 & 25 1844
 on the Bk Royal Earl Master Bell
 Tonnage 315 Built at Sunderland When built 1836
 By whom built _____ Owners W. Ash
 Port belonging to Exeter Destined Voyage Batavia
 If Surveyed Afloat or in Dry Dock Bullhead Dock

Last Survey, No. 10429 Classed 10 A 1

Port London

REPAIRS Wales, topsides and shear stake renewed, and caulked from the lower stake of wales to the beam next the waterway and a general overhaul in the hull & rigging

Present Condition of the

Decks	Transoms <u>Sound</u>	Windlass <u>Good</u>
Upper Deck Beams & Fastenings	Timbers of the Frame <u>Sound & true</u>	Capstan <u>"</u>
Lower Deck Beams & Fastenings	Topsides <u>Good</u>	Pumps <u>"</u>
Spirketting	Wales <u>"</u>	Masts, Yards, &c. <u>"</u>
Plank Shears <u>Good</u>	Counter <u>"</u>	Sails <u>Well found</u>
Waterways	Plank and Treenails <u>"</u> (Outside to the Water's Edge)	Cables <u>"</u>
Hatchway Comings	Rudder <u>"</u>	Anchors No. of <u>3 Bowers 1 Stem 2 Heavy</u>
Breasthooks	Copper <u>Y/A</u>	Standing & Running Rigging <u>good</u>

General Observations and Opinion, Appears in a good & efficient state to retain her present class

W. Ash

The Amount of Fee.....£ : : is received by me,

Committee's Minute 29th Nov 1844

Character assigned 10 A 1

W. Ash



© 2019

Lloyd's Register
Foundation

LONG18-0175