

# REPORT of SURVEY for REPAIRS.

Rec 14 Nov

11233  
H

No. 611 Survey held at London Date November 1844  
on the Sr Columbian Packet Master \_\_\_\_\_  
Tonnage 204 Built at London When built 1824  
By whom built \_\_\_\_\_ Owners Benson & Co  
Port belonging to London Destined Voyage \_\_\_\_\_  
If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 9779 Restored 1842 Classed PA1

Port London

REPAIRS In consequence of having been on shore has had new false keel  
hung in shoes, the keel seam & two seams above it caulked and  
the keel & one sheet above <sup>re</sup> sheathed with yellow metal over paper.

## Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c. <u>Good</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Sails <u>Good</u>
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables <u>Sufficient</u>
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>Yellow Metal 1843</u> <u>Good</u>	Standing & Running Rigging

General Observations and Opinion, Is in a very good & efficient state to retain her present shape

W. W. W. W.

The Amount of Fee.....£..... is received by me,

Committee's Minute 10th Dec 1844

Character assigned As P S A

1 view of Dams  
Lloyd's Register  
Foundation  
LONG 68 - 0240



© 2019