

ANNUAL SURVEYS.

11291

No. 155 Survey held at London Date 15th Jan^y 1845
 on the Ship "Caroline" Master Williams
 Tonnage 330 Built at Cochin When built 1825
 By whom built _____ Owners C Hainbank & Son
 Port belonging to London Destined Voyage Mauritius
 If Surveyed Afloat or in Dry Dock in the West India Dock

Last Survey, No. 11150 Port of London

Classed A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>—</u>	Timbers of the Frame <u>—</u>	Pumps <u>—</u>
Lower Deck Beams & Fastenings <u>—</u>	Topsides <u>—</u>	Masts, Yards, &c. <u>Sufficient</u>
Spirketting <u>Upper Deck new</u>	Wales <u>—</u>	Sails <u>—</u>
Plank Shears <u>—</u>	Counter <u>—</u>	Cables <u>—</u>
Waterways <u>—</u>	Plank and Treenails (Outside to the Water's Edge.) <u>—</u>	Anchors No. of <u>3 B 1 D 1 K</u>
Hatchway Comings <u>—</u>	Rudder <u>Overhauled</u>	Standing & Running Rigging <u>Sufficient</u>
Breasthooks <u>—</u>	Windlass <u>—</u>	Copper <u>Y Metal. New Dec^r 1845</u>

General Observations and Opinion,
as required by the Instructions,

*This Vessel is in efficient Condition and fit for
the safe Conveyance of dry & perishable Cargoes
to & from all parts of the world and may continue*

Committee Minute 17th Jan^y 1845 as closed

Character assigned A 1 *Refer to*

No. 566 Survey held at London Date 11 Jan^y 1845
 on the Bark Mary Pannatype Master Picken
 Tonnage 433 Built at Bridport When built 1840
 By whom built _____ Owners Pannatype
 Port belonging to Limerick Destined Voyage China
 If Surveyed Afloat or in Dry Dock in Mr Fitchers Dock

Last Survey, No. 40199 Port of London

Classed 10 A \

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>—</u>	Timbers of the Frame <u>—</u>	Pumps <u>—</u>
Lower Deck Beams & Fastenings <u>—</u>	Topsides <u>—</u>	Masts, Yards, &c. <u>Sufficient</u>
Spirketting <u>—</u>	Wales <u>—</u>	Sails <u>—</u>
Plank Shears <u>—</u>	Counter <u>—</u>	Cables <u>—</u>
Waterways <u>Caulked</u>	Plank and Treenails (Outside to the Water's Edge.) <u>—</u>	Anchors No. of <u>—</u>
Hatchway Comings <u>—</u>	Rudder <u>—</u>	Standing & Running Rigging <u>—</u>
Breasthooks <u>—</u>	Windlass <u>—</u>	Copper <u>Y Metal Patched</u>

General Observations and Opinion,
as required by the Instructions,

*This Vessel is in efficient Condition and may
continue as closed*

Committee Minute 17th Jan^y 1845

Character assigned 10 A \