

ANNUAL SURVEYS.

11307
Recd 15 Feb

No. 166 Survey held at London Date 5th & 14th Feb 1845
on the Ship Edward Thorne Master R T Johnston
Tonnage 420 Built at Nova Scotia When built 1835
By whom built _____ Owners Marwood
Port belonging to Whitby Destined Voyage North American
If Surveyed Afloat or in Dry Dock on Mr Cardus Way

Last Survey, No. 902 Port of Bristol

Classed A1
SS 1841 4 yrs

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>—</u>	Timbers of the Frame <u>—</u>	Pumps <u>one new</u>
Lower Deck Beams & Fastenings <u>—</u>	Topsides <u>—</u>	Masts, Yards, &c. <u>New Main mast & New Main & 1st & 2nd sufficient</u>
Spirkettling <u>—</u>	Wales <u>Caulked</u>	Sails <u>Sufficient</u>
Plank Shears <u>Caulked</u>	Counter <u>—</u>	Cables <u>New 8' warp</u>
Waterways <u>—</u>	Plank and Treenails <u>—</u> (Outside to the Water's Edge.)	Anchors No. of <u>4 B 1 & 2 K</u>
Hatchway Comings <u>—</u>	Rudder <u>overhauled</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>—</u>	Windlass <u>Good</u>	Copper <u>1 Metal repaired</u>

General Observations and Opinion,
as required by the Instructions,

This Vessel appears in efficient Condition and fit to be Continued as Clipped

Committee Minute 18th Feb 1845

Character assigned A1

W. H. Hatcher
Thornbury

No. 30 Survey held at London Date 10 Feb 1845
on the Brig "Rampier" Master Hutchinson
Tonnage 279 Built at Sunderland When built 1837
By whom built _____ Owners Hutchinson
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock in Mr Dousons Dock

Last Survey, No. 10532 Port of London

Classed A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>—</u>	Timbers of the Frame <u>—</u>	Pumps <u>—</u>
Lower Deck Beams & Fastenings <u>—</u>	Topsides <u>—</u>	Masts, Yards, &c. <u>Sufficient</u>
Spirkettling <u>—</u>	Wales <u>Caulked & treenails overhauled some renewed</u>	Sails <u>—</u>
Plank Shears <u>—</u>	Counter <u>Good</u>	Cables <u>—</u>
Waterways <u>—</u>	Plank and Treenails <u>—</u> (Outside to the Water's Edge.)	Anchors No. of <u>—</u>
Hatchway Comings <u>—</u>	Rudder <u>—</u>	Standing & Running Rigging <u>—</u>
Breasthooks <u>—</u>	Windlass <u>—</u>	Copper <u>1062 Patches & dressed</u>

General Observations and Opinion,
as required by the Instructions,

This Vessel being in efficient Condition may be Continued as Clipped

Committee Minute 18th Feb 1845

Character assigned A1

W. H. Hatcher



© 2019

Lloyd's Register
Foundation