

REPORT of SURVEY for REPAIRS.

& Change of Owners

11387

No. *563* Survey held at *Sandon* Date *Feb 27* 184*5*
 on the *Bn John & Mary* Master *J Samzed*
 Tonnage *103* Built at *Milford* When built *1839*
 By whom built _____ Owners *Tilly & Co*
 Port belonging to *Dartmouth* Destined Voyage *Newfoundland*
 If Surveyed Afloat or in Dry Dock *Sandon Dock*

Last Survey, No. *6980* 1840 Classed *12A1*

Port *Sandon*

REPAIRS *Caulked and sheathed with Yellow Metal over paper*

Present Condition of the

Decks <i>Good</i>	Transoms <i>Sound</i>	Windlass
Upper Deck Beams & Fastenings //	Timbers of the Frame <i>sound when seen</i>	Capstan
Lower Deck Beams & Fastenings //	Topsides <i>Good</i>	Pumps
Spirkettling <i>Good</i>	Wales //	Masts, Yards, &c. <i>Good</i>
Plank Shears //	Counter //	Sails <i>sufficient</i>
Waterways //	Plank & Treenails <i>Good</i> (Outside to the Water's Edge)	Cables
Hatchway Comings //	Rudder //	Anchors No. of
Breasthooks //	<i>Repair Yellow Metal 1845 Feb</i>	Standing & Running Rigging

General Observations and Opinion, *From her general firm & efficient state I am of opinion she may retain her present class*

The Amount of Fee.....£ — : 10 : — is received by me, *W. H. Hatcher*

Committee's Minute _____ 18

Character assigned *12A1*

Record of m. l. p.



© 2019

Lloyd's Register Foundation

LONG 18-0401