

ANNUAL SURVEYS.

11417

No. 592 Survey held at London Date March 7th 1845
 on the Codrington B³ Master Huxtable
 Tonnage 210 Built at Bristol When built 1827
 By whom built _____ Owners Liggins & Co
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dorson's Dock

Last Survey, No. 9085 Port of London Classed 10th AE.1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirketting	Wales <u>inefficiently patched & fixed</u>	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper <u>1839</u> <u>heavily patched, on over time allowed by the rules.</u>

General Observations and Opinion,
 as required by the Instructions,

On the 7th inst notice was sent to the Owners to strip the copper
 it having been on beyond the period permitted by the Rules of the Society.
 and on the 11th the Owners attention was called, by letter, to the state
 of the deck fastenings some of which had been driven out in the course
 of a very inefficient repair of the beams. The report is therefore in our
 opinion that it is in state to remain as classed.
 Expunge Character Augustin Bruce deposed
20 March for ten years notice by letter

No. _____ Survey held at _____ Date _____ 184
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirketting	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions,

Committee Minute _____ 184

Character assigned _____



© 2019

Lloyd's Register
 Foundation

LON 618-0433