

ANNUAL SURVEYS.

11468

Recd 14 April

No. 111 Survey held at London Date 22^d 51 Mar 1845
 on the Ship Cassington Park Master _____
 Tonnage 1441 Built at Southampton When built 1811
 By whom built _____ Owners Carter
 Port belonging to London Destined Voyage Quebec
 If Surveyed Afloat or in Dry Dock in Limekiln Dock

Last Survey, No. 9579 Port of London Classed *A. 1

The Surveyor is required to state the present Condition of the

Decks <u>firm</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>D</u>	Timbers of the Frame <u>—</u>	Pumps <u>—</u>
Lower Deck Beams & Fastenings <u>D</u>	Topsides <u>—</u>	Masts, Yards, &c. <u>New main & upper Mast others left</u>
Spirkettling <u>D</u>	Wales <u>—</u>	Sails <u>Sufficient</u>
Plank Shears <u>D</u>	Counter <u>—</u>	Cables <u>—</u>
Waterways <u>D</u>	Plank and Treenails <u>bottom doubled 1834</u>	Anchors No. of <u>—</u>
Hatchway Comings <u>Good</u>	Rudder <u>two new trunks</u>	Standing & Running Rigging <u>—</u>
Breasthooks <u>—</u>	Windlass <u>—</u>	Copper <u>Stripped & not recoppered</u>

General Observations and Opinion, at Present the Copper stripped off & doubling Caulked and
 as required by the Instructions, not recoppered Three of the Head taken down New upper
pieces of Stem and Apron fitted and Head not replaced 5 half upper
deck and 3 new second hand lower deck beams fitted five new rougher
stanchions with tails & bulwarks fitted abreast of main Mast
 Committee Minute 8th April 1845

Character assigned Reduced to A. 1 This Vessel is in efficient Condition fit for
the safe conveyance of dry & perishable
omitting cottons & cargoes - but from the generally state of her
ex beams & knees & ceiling we think she should
be reduced from the deepthony with the attached
to the Class A. 1

No. _____ Survey held at _____ Date 1845
 on the _____ Master J. H. Piche
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The Surveyor is required to state the present Condition of the

Decks _____	Transoms _____	Capstan _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Pumps _____
Lower Deck Beams & Fastenings _____	Topsides _____	Masts, Yards, &c. _____
Spirkettling _____	Wales _____	Sails _____
Plank Shears _____	Counter _____	Cables _____
Waterways _____	Plank and Treenails _____	Anchors No. of _____
Hatchway Comings _____	(Outside to the Water's Edge.)	Standing & Running Rigging _____
Breasthooks _____	Rudder _____	Copper _____
	Windlass _____	

General Observations and Opinion,
 as required by the Instructions,

Committee Minute _____ 184

Character assigned _____



© 2019

Lloyd's Register
 Foundation

LONG 18-0486