

REPORT of SURVEY for REPAIRS.

No. 388 Survey held at London Date Feb^y 22 to March 1845
on the St. Liam Master Ralsey
Tonnage 455 Built at Newcastle When built 1840
By whom built — Owners Bertram
Port belonging to Newcastle Destined Voyage —
If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 10138 Classed 10 A
Port London

REPAIRS

1845 New fore piece of Kelson and New Rider Kelson off I Deck
Keen Knee secured Ship generally overhauled Caulked from the
Copper up new Bulwarks - new Rudder, New fore Mast & Bowsprit

Present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Windlass <u>Efficient</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>do</u>	Capstan <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>Good</u>	Pumps <u>do</u>
Spirketting <u>Good</u>	Wales <u>do</u>	Masts, Yards, &c. <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Sails <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u>	Cables <u>do</u>
Hatchway Comings <u>do</u>	(Outside to the Water's Edge)	Anchors No. of <u>do</u>
Breasthooks <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
	Copper <u>1843 patched & good</u>	

General Observations and Opinion, She is now in an efficient condition, and
may remain as classed Fourteen

The Amount of Fee.....£ 2 : — : — is received by me, —

Committee's Minute 11th April 1845

Character assigned 10 A

Record Damage repairs
—



© 2019

Lloyd's Register
Foundation
LON618-10492