

ANNUAL SURVEYS.

11491

Rep^d 17 April

No. ⁵¹⁶ Survey held at London Date April 11 to April 16 1845
 on the Royalist B.E. Master David Murray
 Tonnage 226 Built at Phymouth When built 1842
 By whom built _____ Owners J Hamilton
 Port belonging to London Destined Voyage Africa
 If Surveyed Afloat or in Dry Dock In Pletcher's Dock

Last Survey, No. 1053 Port of London Classed 12 A1

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms <u>good</u>	Capstan _____
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u>good when seen</u>	Pumps <u>in good order</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides _____	Masts, Yards, &c. <u>"</u>
Spirketting <u>"</u>	Wales _____	Sails <u>2 suits</u>
Plank Shears <u>"</u>	Counter <u>good</u>	Cables <u>200 ft Chain & Stream & 3 good lumps</u>
Waterways <u>"</u>	Plank and Treenails <u>(Outside to the Water's Edge.)</u>	Anchors No. of <u>3 B. 1 S. and 3 K.</u>
Hatchway Comings <u>"</u>	Rudder <u>Has been unhung & refitted</u>	Standing & Running Rigging <u>in good order</u>
Breasthooks <u>"</u>	Windlass <u>in good order</u>	Copper <u>has been ex'd & repaired</u>

General Observations and Opinion,
as required by the Instructions,

Her copper has been examined & repaired - her rudder unhung and a new metal upper finial & brass fitted the original having been of iron. Her topsides have been caulked and she is in an efficient state and in good condition to remain as classed.

Committee Minute 18th April 1845

Character assigned 12 A1

Aug 2 Brewer
J B Hatcher

No. 904 Survey held at London Date April 16 1845
 on the Sydney B.E. Master White
 Tonnage 345 Built at Glasgow When built 1840
 By whom built _____ Owners A & J Kidson
 Port belonging to Glasgow Destined Voyage Quebec
 If Surveyed Afloat or in Dry Dock In Pletcher's Dock

Last Survey, No. 10129 Port of London Classed 10 A1

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms <u>good</u>	Capstan <u>(small) good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>very good when seen</u>	Pumps <u>in good order</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>good</u>	Masts, Yards, &c. <u>in good condition</u>
Spirketting <u>"</u>	Wales <u>good</u>	Sails <u>2 suits</u>
Plank Shears <u>"</u>	Counter <u>good</u>	Cables <u>210 ft Chain & good Hawser</u>
Waterways <u>"</u>	Plank and Treenails <u>(Outside to the Water's Edge.)</u>	Anchors No. of <u>3 Power 1 Stream 1 Kedge</u>
Hatchway Comings <u>"</u>	Rudder <u>Ex 2</u>	Standing & Running Rigging <u>in good order</u>
Breasthooks <u>"</u>	Windlass <u>In good order</u>	Copper <u>Y.M. in good order</u>

General Observations and Opinion,
as required by the Instructions,

This vessel has had her bottom examined in a dry dock, she is in good condition, and we are of opinion may remain as classed.

Committee Minute 18th April 1845

Character assigned 10 A1

Augustin Brewer
J B Hatcher