

ANNUAL SURVEYS.

11558

No. 614 Survey held at London Date May 6th 7th 184 5
 on the Thymen Bⁿ Master Mainland
 Tonnage 344 Built at Sunderland When built 1826
 By whom built _____ Owners Chas. Walton
 Port belonging to London Destined Voyage North America
 If Surveyed Afloat or in Dry Dock Dock

Last Survey, No. 10389 Port of London Classed *AE1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion,
as required by the Instructions,

On the 7th of this month notice was given to the Owners that in consequence of the great working in the securities of the Hold beams - additional fastening was required, and also that it would be desirable to fit a crutch & a pair of Pinners. Her bottom has been stripped and blacked down but the notices have not been complied with and the ship has sailed for North America.

Committee Minute

Character assigned

16th May 1845
20th May 1845
Refused to F.S. & placed in Augustin Breeze.
20th May
20th May

No. _____ Survey held at _____ Date _____ 184 _____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion,
as required by the Instructions,

Committee Minute

184

Character assigned



© 2019

Lloyd's Register
Foundation