

# ANNUAL SURVEYS.

11569  
Recd 14 May 1845

No. 88 Survey held at London Date May 14<sup>th</sup> 1845 1845  
on the Malvina B<sup>d</sup> Master Burton  
Tonnage 186 Built at Kythe When built 1825  
By whom built  Owners Barrett & Blakesley  
Port belonging to London Destined Voyage Tifricia  
If Surveyed Afloat or in Dry Dock Stoneham's Ways

Last Survey, No. 5230 Port of Liverpool Classed FEI

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms <u>good</u>	Capotom <u></u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u>good when seen</u>	Pumps <u>in good order</u>
Lower Deck Beams & Fastenings <u>good</u>	Topsides <u>good - caulking very good</u>	Masts, Yards, &c. <u>good, new M. Mast &amp; M. Yard</u>
Spirketting <u>good</u>	Wales <u>good - caulked</u>	Sails <u>2 suits - several new sails</u>
Plank Shears <u>good</u>	Counter <u>good</u>	Cables <u>180 fms Hemp Stream &amp; 2 good Hawser</u>
Waterways <u>good - built caulked</u>	Plank and Treenails <u>good</u> (Outside to the Water's Edge.)	Anchors No. of <u>3 B. 1 S. 1 kedge</u>
Hatchway Comings <u>good</u>	Rudder <u>examined in good order</u>	Standing & Running Rigging <u>overhauled</u>
Breasthooks <u>good</u>	Windlass <u>refitted</u>	Copper <u>Y.M. repaired</u>

General Observations and Opinion,

as required by the Instructions, This ship has been on the ways & her keel bottom examined and the Y.M. repaired - She has had a new pair of iron pointers fitted, and a new iron keel & the beam abate the fore mast - She is in good condition, and fit to carry dry & perishable cargoes to & from all parts of the

Committee Minute 20th May 1845 board, and we consider may remain as classed  
Character assigned FEI with the asterisk Augustus Beechey

Four tenay

No. 460 Survey held at London Date May 16<sup>th</sup> 1845  
on the Elizabeth Muchham B<sup>d</sup> Master Bewley  
Tonnage 242 Built at Whitehaven When built 1837  
By whom built  Owners Bewley & Son 23 Newell  
Port belonging to London Destined Voyage Sydney  
If Surveyed Afloat or in Dry Dock On Dawson's slips

Last Survey, No. 10623 Port of London Classed 10A1

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms <u>good</u>	Capotom <u></u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u>good when seen</u>	Pumps <u>good</u>
Lower Deck Beams & Fastenings <u>good</u>	Topsides <u>good</u>	Masts, Yards, &c. <u>good</u>
Spirketting <u>good</u>	Wales <u>good</u>	Sails <u>2 suits</u>
Plank Shears <u>good</u>	Counter <u>good</u>	Cables <u>200 Chain Hemp Stream &amp; 2 good Hawser</u>
Waterways <u>good</u>	Plank and Treenails <u>good</u> (Outside to the Water's Edge.)	Anchors No. of <u>3 B. 1 S. 2 kedges</u>
Hatchway Comings <u>good</u>	Rudder <u>examined in good order</u>	Standing & Running Rigging <u>in good order condition</u>
Breasthooks <u>good</u>	Windlass <u>in good order</u>	Copper <u>Y.M. repaired</u>

General Observations and Opinion,

as required by the Instructions, This ship is in good condition and we are of opinion may remain as at present classed.

Committee Minute 20th May 1845

Character assigned 10A1

Augustus Beechey  
Four tenay

© 2019  
Lloyd's Register  
Foundation