

REPORT of SURVEY for REPAIRS.

No. 36 Survey held at London Date 9th May 1845
 on the Bark "Achilles" Master Trevellick
 Tonnage 252 Built at Bristol When built 1820
 By whom built _____ Owners W. Tindall
 Port belonging to London Destined Voyage Coast of Africa
 If Surveyed Afloat or in Dry Dock in W. Tindall's Dock

Last Survey, No. 10258

Classed * E 1

Port London

REPAIRS at present Cutter & Head taken down. New front piece fitted on Stem & Head not replaced. New Knightheads and Kaute timbers fitted on both sides and upper end of Apron piece - two new wooden breast hooks fitted. Several pieces of the doubling of topsides shifted forward. New deck laid down before the windlass and under bowsprit new fore scuttle, windlass belines and new Purchase fitted to it. Main piece of Rudder hooped and bands overhauled & refitted. Doubling of bottom above the upper edge of the Y Metal refastened and it and the doubling of the Wals and topsides caulked. Y Metal of bottom has been dropped and patched. New bowsprit and Topmast yards furnished. Chambers of Pumps bored out.

Present Condition of the

Decks <u>Good</u>	Treenails <u>Not seen</u>	Windlass and Capstan <u>Refitted</u>
Waterways <u>Caulked</u>	Breasthooks and Stemson <u>Good</u>	Pumps <u>Overhauled Good</u>
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. <u>Sufficient</u>
Lower Deck Beams & Fastenings _____	Keelsons <u>Pieced</u>	Sails _____
Planksheers <u>Part new fore</u>	Clamps and Shelves _____	Anchors No. of <u>3 B 1st 1 R</u>
Sheerstrakes _____	Ceiling _____	Cables <u>90 fath of 1 1/2 New</u>
Topsides <u>Old doubling Caulked</u>	Rudder <u>overhauled</u>	Hawsers and Warps <u>Suff</u>
Wales <u>D. D. D.</u>	Copper <u>Y Metal patched</u>	Standing & Running Rigging <u>Refitted</u>
Plank (Bottom) and Counter <u>Not seen</u>		

General Observations and Opinion,

This Vessel's doubling being only 1 1/2 inch thick and having been on since 1824 the owner has recommended to strip it off but which he declined doing the state of the bottom plank under it is therefore unknown to me and under the circumstances best to leave her Clipping to the Consulate.

The Amount of Fee.....£ 1 : : is received by me,

W. Tindall

Certificate (if required)

Committee's Minute

30th May 1845

Character assigned

Efficient & seaworthy

Account upon



Lloyd's Register Foundation

00619-0094