

ANNUAL SURVEYS.

11692

No. 123 Survey held at London Date July 5 1845
 on the Ship "Surge" Master J. Burnett
 Tonnage 411 Built at Sunderland When built 1843
 By whom built 550 Owners Phillips
 Port belonging to London Destined Voyage Ascension
 If Surveyed Afloat or in Dry Dock In Messrs' Culling & Young's Dry Dock

Last Survey, No. 1080 Port of London Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms <u>good</u>	Capstan
Upper Deck Beams & Fastenings <u>a^o</u>	Timbers of the Frame <u>a^o</u>	Pumps
Lower Deck Beams & Fastenings <u>a^o</u>	Topsides <u>a^o</u>	Masts, Yards, &c.
Spirkettling <u>a^o</u>	Wales <u>a^o</u>	Sails
Plank Shears <u>a^o</u>	Counter <u>a^o</u>	Cables
Waterways <u>a^o</u>	Plank and Treenails <u>a^o</u> (Outside to the Water's Edge.)	Anchors No. of <u>3</u> <u>11</u>
Hatchway Comings <u>a^o</u>	Rudder <u>a^o</u>	Standing & Running Rigging
Breasthooks <u>a^o</u>	Windlass <u>a^o</u>	Copper <u>Y.M. 1843</u>

General Observations and Opinion,
 as required by the Instructions,

*Now Caulked entirely above the Copper.
 She is in good condition and should*

Committee Minute 8 July 1845 remain as Class "A 1"

Character assigned 10 A 1 *J. A. Martin*

No. 484 Survey held at London Date July 5th 1845
 on the Bk "John Willis" Master Jas. Willis
 Tonnage 320 Built at Sunderland When built 1839
 By whom built 386 Owners Messrs Willis & Co
 Port belonging to London Destined Voyage Demerara
 If Surveyed Afloat or in Dry Dock In Limekiln Dry Dock

Last Survey, No. 11318 Port of London Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms	Capstan
Upper Deck Beams & Fastenings <u>a^o</u>	Timbers of the Frame <u>good when seen</u>	Pumps
Lower Deck Beams & Fastenings <u>a^o</u>	Topsides <u>a^o</u>	Masts, Yards, &c.
Spirkettling <u>a^o</u>	Wales <u>a^o</u>	Sails
Plank Shears <u>a^o</u>	Counter <u>a^o</u>	Cables
Waterways <u>a^o</u>	Plank and Treenails <u>a^o</u> (Outside to the Water's Edge.)	Anchors No. of <u>3</u> <u>12</u>
Hatchway Comings <u>a^o</u>	Rudder <u>a^o</u>	Standing & Running Rigging
Breasthooks <u>a^o</u>	Windlass <u>a^o</u>	Copper <u>now new upon Felt</u>

General Observations and Opinion,
 as required by the Instructions,

*The Yellow Metal Sheathing now stripped
 off. The Bottom Caulked and resheathed
 with Copper upon Felt.*

Committee Minute 8 July 1845

Character assigned 10 A 1 *J. A. Martin*