

# ANNUAL SURVEYS.

11760  
Rec<sup>d</sup> July

No. 463 Survey held at London Date July 29 1845  
on the By Amy Master Crane  
Tonnage 160 Built at Poole When built 1840  
By whom built \_\_\_\_\_ Owners Bloomfield  
Port belonging to London Destined Voyage Seaham  
If Surveyed Afloat or in Dry Dock Afloat Katherine's Dock

Last Survey, No. 10363 Port of London

Classed A, 1st class  
44

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan _____
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound &amp; staunch</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. _____
Spirketting <u>Good</u>	Wales <u>"</u>	Sails <u>Well found</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper _____

General Observations and Opinion, Shew no symptoms of weakness or decay, and from her  
as required by the Instructions, very firm and efficient state I am of opinion she is fit  
for the safe conveyance of dry & perishable cargoes  
& from all parts of the world and may retain her  
present class

Committee Minute 1st August 1845

Character assigned A, 1st class

No. 466 Survey held at London Date July 30<sup>th</sup> 1845  
on the By Ellen Master McEachern  
Tonnage 230 Built at Perth When built 1836  
By whom built \_\_\_\_\_ Owners Richbell  
Port belonging to London Destined Voyage Demerara  
If Surveyed Afloat or in Dry Dock West India Dock

Last Survey, No. 10953 Port of London

1844 Continued Classed Three years A

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound &amp; staunch</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirketting <u>"</u>	Wales <u>"</u>	Sails <u>Well found</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>Good</u> (Outside to the Water's Edge.)	Anchors No. of <u>3 Bows 1 Stm 2 Hedges</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>Yellow Metal 4044</u>

General Observations and Opinion, Has been in the dry dock and bottom examined and is  
as required by the Instructions, throughout in a very efficient state to retain her  
present character

Committee Minute 1st August 1845

Character assigned C, 3rd class

