

ANNUAL SURVEYS.

11871

No. ³⁹⁰ Survey held at London Date September 4th to 9th 1845
 on the Sr. Hangerford Master Piggitt
 Tonnage 736 Built at Calcutta When built 1813
 By whom built _____ Owners C. Ferguson
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Wigams Dock

Last Survey, No. 10335 Port of London

Classed E, 1 Roberts
expunged

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>sound & true</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirketting <u>Good</u>	Wales <u>"</u>	Sails <u>Well found</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>3 Bower 1 Stm 2 Hedges</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>Y.M. Sept. 1845</u>

General Observations and Opinion Having been on shore bottom & shipped, new fore & after piece of
 as required by the Instructions, false keel, hung in place, caulked from the keel to the upper
part of the walls and a general overhaul, we are of opinion
from her very high state of efficiency & her fit for the service,
conveyance of dry & perishable cargoes to & from all parts of
12th Sept. 1845 the world and may retain her present class

Committee Minute _____

Character assigned _____

Special £5.5.0

E, 1 asterisk
W.D. Roberts
Aug. Breuze

No. ³⁶³ Survey held at London Date Sept. 10th to 15th 1845
 on the Bk. Rozier Master Pollock
 Tonnage 575 Built at Greenock When built 1830
 By whom built _____ Owners Anderson
 Port belonging to Greenock Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Wigams Dock

Last Survey, No. 1394 Port of Glyde

Classed 12A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>sound & true</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirketting <u>"</u>	Wales <u>"</u>	Sails <u>Good</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>Sufficient</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>"</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>7 September 1845</u>

General Observations and Opinion, Bottom caulked and covered over felt in the upper course
 as required by the Instructions, and proper below, and she appears in all respects in a
good condition to continue in her present class

Committee Minute _____

Character assigned _____

12th Sept. 1845

12A1

record Copper



© 2019

Lloyd's Register
 Foundation

LON619-0364