

ANNUAL SURVEYS.

11960

Rec. 16 Oct.

No. 11663 Survey held at London Date Oct 15 1845
 on the "Malay" Master Smith
 Tonnage 297 Built at Leeds When built 1834
 By whom built London Owners London & Co
 Port belonging to London Destined Voyage South America
 If Surveyed Afloat or in Dry Dock by dock & afloat

Last Survey, No. 11663 Port of London

Classed S.F. 1
S.S. 42 - 5. 1/2

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Secure</u>	Timbers of the Frame <u>do</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>efficient</u>
Spirketting <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper ed <u>1845</u>

General Observations and Opinion, 1845 bottom caulked and sheathed with copper nails
as required by the Instructions,
She appears in good and efficient condition fit for the conveyance
of dry & perishable cargoes from all parts of the World. & may
 Committee Minute 17th Oct 1845 remain as before
 Character assigned 1st Class Fourteen

No. 11197 Survey held at London Date 15 Oct 1845
 on the "Gulford" Master Haymer
 Tonnage 313 Built at Shields When built 1840
 By whom built London Owners Gordonson
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock afloat

Last Survey, No. 11197 Port of London

Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Secure</u>	Timbers of the Frame <u>do</u>	Pumps <u>efficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>do</u>	Masts, Yards, &c. <u>do</u>
Spirketting <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper ed <u>1844</u>

General Observations and Opinion, Is in an efficient condition and may remain
as required by the Instructions,
as before

Committee Minute 17th Oct 1845

Character assigned 10 A 1



© 2019

Lloyd's Register
 Foundation