

# ANNUAL SURVEYS.

12000

No. 10 Survey held at Londra Date Oct 24<sup>th</sup> 1845  
 on the St. Gallway Lass Master in Port  
 Tonnage 278 Built at Amsterdam When built 1839  
 By whom built — Owners Agilly  
 Port belonging to Londra Destined Voyage —  
 If Surveyed Afloat or in Dry Dock Cruising

Dec 24/45

Last Survey, No. 9059 Port of Londra Classed 1st A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>—</u>
Upper Deck Beams & Fastenings <u>Secure</u>	Timbers of the Frame <u>do</u>	Pumps <u>Efficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topides <u>do</u>	Masts, Yards, Sc. <u>do</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treennails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>None</u>

General Observations and Opinion,  
 as required by the Instructions,

The Copper now shipped off bottom looks but not weeped. The Iron bolts driven out of the hanging knees of the Wood Bins and replaced with Copper as in an efficient

Committee Minute 10<sup>th</sup> Dec 1845 Condition and May unseen

Character assigned 10<sup>th</sup> Dec as Efficient Fourteen

No. 321 Survey held at Londra Date Oct 28 1845  
 on the St. Iriad Master Brown  
 Tonnage 307 Built at Amsterdam When built 1843  
 By whom built — Owners Smith  
 Port belonging to Port Destined Voyage —  
 If Surveyed Afloat or in Dry Dock Afloat

11

Last Survey, No. 2057 Port of Londra Classed 1st A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>—</u>
Upper Deck Beams & Fastenings <u>Secure</u>	Timbers of the Frame <u>—</u>	Pumps <u>Efficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topides <u>—</u>	Masts, Yards, Sc. <u>do</u>
Spirkettling <u>Good</u>	Wales <u>—</u>	Sails <u>do</u>
Plank Shears <u>—</u>	Counter <u>—</u>	Cables <u>do</u>
Waterways <u>—</u>	Plank and Treennails <u>—</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>—</u>	Rudder <u>—</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>—</u>	Windlass <u>—</u>	Copper <u>None</u>

General Observations and Opinion,  
 as required by the Instructions,

Is in an efficient Condition May unseen

Committee Minute 10<sup>th</sup> Dec 1845

Character assigned 10<sup>th</sup> Dec

Lloyd's Register  
 Foundation

Lon 620-0040